

c2JpbGV0c2t5aTsyMDIxLTA2LTAyVDE0OjEwOjIxLjIwMFo7MTg1LjIxMC44Ni4yMjItTQUxDQTJCTjFKSDc1OTUwOA==

C3R221 : Sensor-Side impact-Rear-Left

Connector Face

Click to toggle focus





Connector

C3R221

Housing	**Serviceable** **Overlay not available**
Engineering Part Number	8X2T-14A464-HA
Service Part Number	YPC801710
Colour	BLACK
Cavities	2
Harness	CABIN LH HARNESS
Description	Sensor-Side impact-Rear-Left
Location	Left C-pillar

Wire chart and service repair kit information

CAV	CSA	COL	CCT	DESTN	Pre-Terminated Lead	Extract Tool	Crimpers	Wire Stripper	Heat Shrink Sleeve	Ident Sleeve	Splice
1	0.35	BU-GN	ALL	C3R114	418-940	-	418-116A	418-672	418-104	418-112	418-107
2	0.35	GN-BN	ALL	C3R114	418-940	-	418-116A	418-672	418-104	418-112	418-107