

c2JpbGV0c2t5aTsyMDIxLTA2LTAyVDE1OjQxOjU4Ljc1NVo7MTg1LjIxMC44NI4yMjTQUxDQTJCTjFKSDc1OTUwOA==

CAR217 : Sensor-Impact pressure-Front door-Right

Connector Face

Click to toggle focus





Housing	**Serviceable** **Overlay not available**
Engineering Part Number	8X2T-14A464-HA
Service Part Number	YPC801710
Colour	BLACK
Cavities	2
Harness	DRIVER DOOR LHD HARNESS
Description	Sensor-Impact pressure-Front door-Right
Location	Behind driver door trim panel
Qualifier	LHD condition illustrated

Connector
CAPW02A
CAPW02B
C3AG
CAR217
CAPW10
CAPS15
CAPW11
CAPK09
C3AD
CALN45
C3AB
CALN41M
CALN41
CAPL22
CAPK23
CAPM26A
CAPM26AM
CAPL63
CALN45BM
CALN45B

Wire chart and service repair kit information

CAV	CSA	COL	CCT	DESTN	Pre-Terminated Lead	Extract Tool	Crimpers	Wire Stripper	Heat Shrink Sleeve	Ident Sleeve	Splice
1	0.35	BK	ALL	C3AB	418-940	-	418-116A	418-672	418-104	418-112	418-107
2	0.35	BK	ALL	C3AB	418-940	-	418-116A	418-672	418-104	418-112	418-107