

c2JpbGV0c2t5aTsyMDIxLTA2LTAyVDEzOjMxOjI0LjEwMIo7MTg1LjIxMC44Ni4yMjITQUxDQTJCTjFKSDc1OTUwOA==

C23A : Instrument panel harness to link harness

Connector Face





Connector
C23B
C23A
C3DC07
C33K
C3BC09
C33J
C33H
C33G
C3ET42

Housing	**Serviceable Overlay not available**
Engineering Part Number	1S7T-14489-TB
Service Part Number	LR146533
Colour	GREEN
Cavities	22
Harness	INSTRUMENT PANEL LHD HARNESS
Description	Instrument panel harness to link harness
Location	Beneath center console

Wire chart and service repair kit information

CAV	CSA	COL	CCT	DESTN	Pre-Terminated Lead	Extract Tool	Crimpers	Wire Stripper	Heat Shrink Sleeve	Ident Sleeve	Splice
1	0.75	GY-RD	TR-XN	S2BP69	418-235	418-595	418-116A	418-672	418-104	418-112	418-107
2	0.5	GN-OG	TR-XN	S2BP22	418-235	418-595	418-116A	418-672	418-104	418-112	418-107
3	0.5	GN-WH	TR-XN	S2ET21	418-235	418-595	418-116A	418-672	418-104	418-112	418-107
4	0.5	GY-BN	TR-XN	C21C	418-235	418-595	418-116A	418-672	418-104	418-112	418-107

CAV	CSA	COL	CCT	DESTN	Pre-Terminated Lead	Extract Tool	Crimpers	Wire Stripper	Heat Shrink Sleeve	Ident Sleeve	Splice
5	0.13	GN-OG	TR-XN	S2DB25E	418-265	418-659	418-116A	418-672	418-104	418-112	418-107
6	0.13	GY-BU	TR-XN	S2DB26E	418-265	418-659	418-116A	418-672	418-104	418-112	418-107