

c2JpbGV0c2t5aTsyMDIxLTA2LTAyVDEzOjM1OjE1Ljg4OFo7MTg1LjIxMC44Ni4yMjITQUxDQTJCTjFKSDc1OTUwOA==

C2LF23B : Switch-Auxiliary lighting

Connector Face





Connector
G6D139
C2LF23A
C2MC57A
C2LF23C
C2MC56A
C2LF23B

Housing	**Serviceable Overlay not available**
Engineering Part Number	6W8T-14489-AFA
Service Part Number	YPC106460
Colour	GREEN
Cavities	10
Harness	INSTRUMENT PANEL LHD HARNESS
Description	Switch-Auxiliary lighting
Location	Behind driver side of Instrument panel
Qualifier	LHD condition illustrated

Wire chart and service repair kit information

CAV	CSA	COL	CCT	DESTN	Pre-Terminated Lead	Extract Tool	Crimpers	Wire Stripper	Heat Shrink Sleeve	Ident Sleeve	Splice
1	0.35	BN	ALL	S2LN17	418-587-02	418-595	418-116A	418-672	418-104	418-112	418-107
2	0.5	BU-GY	ALL	S2BP21	418-587-02	418-595	418-116A	418-672	418-104	418-112	418-107
3	0.5	YE-VT	JBBAB	C21C	418-587-02	418-595	418-116A	418-672	418-104	418-112	418-107

CAV	CSA	COL	CCT	DESTN	Pre-Terminated Lead	Extract Tool	Crimpers	Wire Stripper	Heat Shrink Sleeve	Ident Sleeve	Splice
4	0.35	WH-BN	ALL	C32D	418-587-02	418-595	418-116A	418-672	418-104	418-112	418-107
5	0.35	BU-WH	ALL	C1BP02A	418-587-02	418-595	418-116A	418-672	418-104	418-112	418-107
6	0.35	BU-OG	ALL	C1BP02A	418-587-02	418-595	418-116A	418-672	418-104	418-112	418-107
7	0.75	BK-VT	ALL	C21C	418-587-02	418-595	418-116A	418-672	418-104	418-112	418-107
8	0.5	BK-VT	ALL	S2D134B	418-587-02	418-595	418-116A	418-672	418-104	418-112	418-107