

c2JpbGV0c2t5aTsyMDIxLTA2LTAyVDEzOjM3OjQ2LjAxN1o7MTg1LjIxMC44NHi4yMjtTQUxDQTJCTjFKSDc1OTUwOA==

C2LS41 : Module-Steering wheel

Connector Face

Click to toggle focus





Connector
C2LS41
C2R115D
C2R115E

Housing **Serviceable** **Overlay not available**

Engineering Part Number 7M5J-14489-KEA

Service Part Number YPC106480

Colour GREEN

Cavities 16

Harness INSTRUMENT PANEL LHD HARNESS

Description Module-Steering wheel

Location Behind steering column cowl - LH side

Qualifier LHD condition illustrated

Wire chart and service repair kit information

CAV	CSA	COL	CCT	DESTN	Pre-Terminated Lead	Extract Tool	Crimpers	Wire Stripper	Heat Shrink Sleeve	Ident Sleeve	Splice
1	0.13	BU	ALL	S2DB29A	-	-	-	-	-	-	-
2	0.13	BU-GN	ALL	S2DB30A	-	-	-	-	-	-	-
3	0.35	YE	ALL	C1BP02B	418-587-02	418-595	418-116A	418-672	418-104	418-112	418-107

CAV	CSA	COL	CCT	DESTN	Pre-Terminated Lead	Extract Tool	Crimpers	Wire Stripper	Heat Shrink Sleeve	Ident Sleeve	Splice
4	0.13	WH	ALL	S2MC34	-	-	-	-	-	-	-
5	0.5	BU-WH	ALL	C21C	418-587-02	418-595	418-116A	418-672	418-104	418-112	418-107
7	0.5	BU-RD	ALL	C1BP02C	418-587-02	418-595	418-116A	418-672	418-104	418-112	418-107
8	0.75	BK-VT	ALL	S2D134B	418-587-02	418-595	418-116A	418-672	418-104	418-112	418-107
9	0.13	WH	ALL	S2MC34	-	-	-	-	-	-	-
10	0.35	BU-GN	ALL	C1BP02B	418-587-02	418-595	418-116A	418-672	418-104	418-112	418-107
12	0.5	YE	ALL	C21C	418-587-02	418-595	418-116A	418-672	418-104	418-112	418-107
14	0.35	GY-YE	ICRAD	C3MA01A	418-587-02	418-595	418-116A	418-672	418-104	418-112	418-107
14	0.35	GY-YE	ICRAB/ICRAE	C2ME03A	418-587-02	418-595	418-116A	418-672	418-104	418-112	418-107
16	0.35	BN	ALL	C2MC01A	418-587-02	418-595	418-116A	418-672	418-104	418-112	418-107