
c2JpbGV0c2t5aTsyMDIxLTA2LTAyVDEzOjI4OjU5LjQ2NVo7MTg1LjIxMC44NCI4yMjITQUxDQTJCTjFKSDc1OTUwOA==


C1MP23 : Proximity camera-Front

Connector Face

Click to toggle focus



DARK GREY



Connector
C1MF04
C1MP23

Housing **Not Serviceable** **Overlay not available**

Engineering Part Number DK5T-14A464-NA

Service Part Number

Colour GREY

Cavities 6

Harness FRONT BUMPER HARNESS

Description Proximity camera-Front

Location Behind center of front bumper

Wire chart

CAV	CSA	COL	CCT	DESTN
2	0.35	RD	J3KAE	C11Z
3	0.35	RD	J3KAE	C11Z
5	0.35	BK	J3KAE	C11Z
6	0.35	BK	J3KAE	C11Z

CAV	CSA	COL	CCT	DESTN
SCR	0.35	SCR	J3KAE	C11Z