

c2JpbGV0c2t5aTsyMDIxLTA2LTAyVDEzOjQwOjU5LjY4NIo7MTg1LjIxMC44NiI4yMjtTQUxDQTJCTjFKSDc1OTUwOA==

C2R115C : Clockspring

Connector Face





Connector
C22A
C2X107
C2LS41B
C2LS41C
C2R115F
C2HS71A
C2X108
C2R115C

Housing	**Not Serviceable** **Overlay not available**
Engineering Part Number	CHCT-14489-PA
Service Part Number	
Colour	BLACK
Cavities	11
Harness	STEERING WHEEL HARNESS
Description	Clockspring
Location	Steering Wheel

Wire chart and service repair kit information

CAV	CSA	COL	CCT	DESTN
1	0.35	BU-YE	ALL	S2D134H
2	0.35	YE-VT	ALL	C2LS41C
4	0.35	YE-GY	ALL	C2LS41C
6	0.35	BU	ALL	C22A

CAV	CSA	COL	CCT	DESTN
7	0.35	WH-RD	ALL	C2LS41B
11	0.35	GN-WH	ALL	C2LS41B