

c2JpbGV0c2t5aTsyMDIxLTA2LTAyVDEzOjUxOjM4LjQ5N1o7MTg1LjIxMC44Ni4yMjITQUxDQTJCTjFKSDc1OTUwOA==

C33UA : Instrument panel harness to seat link harness

Connector Face





Connector
C33UA
C33C

Housing **Not Serviceable** **Overlay not available**

Engineering Part Number DHCT-14489-MA

Service Part Number

Colour WHITE

Cavities 6

Harness INSTRUMENT PANEL LHD HARNESS

Description Instrument panel harness to seat link harness

Location Beneath front passenger seat

Qualifier LHD condition illustrated

Wire chart and service repair kit information

CAV	CSA	COL	CCT	DESTN
1	0.14	BN	ICRAD+IENAD	C3MA02B
2	0.14	GN	ICRAD+IENAD	C3MA02B
3	0.14	OG	ICRAD+IENAD	C3MA02B

CAV	CSA	COL	CCT	DESTN
4	0.14	BU	ICRAD+IENAD	C3MA02B
5	0.75	VT	ICRAD+IENAD	C3MA02B
6	0.75	BK	ICRAD+IENAD	C3MA02B
SCR	0.14	SCR	ICRAD+IENAD	C3MA02B