

c2JpbGV0c2t5aTsyMDIxLTA2LTAyVDEzOjU5OjEwLjg1MFo7MTg1LjIxMC44Ni4yMjITQUxDQTJCTjFKSDc1OTUwOA==

C3LN39 : Lamp-Footwell-Front-Right

Connector Face

Click to toggle focus





Connector
C1BP02D
C21A
C1BP02B
C1BP02C
C1BP02A
C31V
C1DC31B
C31U
C1BP02F
C3DC31C
C3DC31A
C32D
C32C
C3LN39
C21B

Housing	**Not Serviceable Overlay not available**
Engineering Part Number	91AG-13K370-AB
Service Part Number	
Colour	BLACK
Cavities	2
Harness	INSTRUMENT PANEL LHD HARNESS
Description	Lamp-Footwell-Front-Right
Location	Behind passenger side of Instrument panel
Qualifier	LHD condition illustrated

Wire chart and service repair kit information

CAV	CSA	COL	CCT	DESTN
1	0.5	GY-VT	JCBAS/JCBAT	S2LN38
2	0.5	BK-YE	JCBAS/JCBAT	S2D139D