
c2JpbGV0c2t5aTsyMDIxLTA2LTAyVDE0OjAzOjAxLjYxN1o7MTg1LjIxMC44Ni4yMjITQUxDQTJCTjFKSDc1OTUwOA==


C3ME22NC : Module-Audio amplifier

Connector Face

Click to toggle focus



GREEN



Connector
C3ME22NC
C3ME22NB
C3ME22NE
C3ME22ND
C3ME22NA

Housing **Not Serviceable** **Overlay not available**

Engineering Part Number DHCT-14489-PA

Service Part Number

Colour GREEN

Cavities 6

Harness INSTRUMENT PANEL LHD HARNESS

Description Module-Audio amplifier

Location Beneath LH Front seat

Wire chart and service repair kit information

CAV	CSA	COL	CCT	DESTN
1	0.14	WH	ICRAD	C3MA01E
2	0.14	WH	ICRAD	C3MA01E
3	0.14	WH	ICRAD	C3MA01E
4	0.14	WH	ICRAD	C3MA01E

CAV	CSA	COL	CCT	DESTN
5	0.35	YE	ICRAD	C3MA01A
SCR	0.14	SCR	ICRAD	C3MA01E