

c2JpbGV0c2t5aTsyMDIxLTA2LTAyVDE0OjEwOjE2LjI2MIo7MTg1LjIxMC44Ni4yMjITQUxDQTJCTjFKSDc1OTUwOA==

C3R216 : Sensor-Seat position-Passenger

Connector Face

Click to toggle focus





Connector
C3HS13A
C3PS71A
C3PS71B
C3PS32C
C3HS09A
C3PS32A
C3R203
C3HS08A
C3HS13AM
C3PS33
C3R216
C3R116
C3PS35
C33D
C3R118
C3PS37

Housing **Serviceable** **Overlay not available**

Engineering Part Number EHCT-14A464-ZA

Service Part Number LR070626

Colour BLACK

Cavities 2

Harness SEAT PASSENGER LHD HARNESS

Description Sensor-Seat position-Passenger

Location Beneath front passenger seat

Qualifier LHD condition illustrated

Wire chart and service repair kit information

CAV	CSA	COL	CCT	DESTN	Pre-Terminated Lead	Extract Tool	Crimpers	Wire Stripper	Heat Shrink Sleeve	Ident Sleeve	Splice
1	0.35	BU-GY	ADTAB	C33D	418-481	418-595	418-116A	418-672	418-104	418-112	418-107
2	0.35	GN-OG	ADTAB	C33D	418-481	418-595	418-116A	418-672	418-104	418-112	418-107