

c2JpbGV0c2t5aTsyMDIxLTA2LTAyVDE1OjIyOjMzLjk1MFo7MTg1LjIxMC44Ni4yMjITQUxDQTJCTjFKSDc1OTUwOA==

C4MP19A : Camera-Rear view

Connector Face

Click to toggle focus





Connector
C4LS36B
C4LS36C
C4MP19A
C4MP19AA
C4MP19B
C4PL17C
C4PL21B
C4PL21BM
C4PL45B
C4RD02C
G4D481A

Housing **Not Serviceable** **Overlay not available**

Engineering Part Number CHCT-14489-EJA

Service Part Number

Colour BLACK

Cavities 6

Harness TAILGATE ICE HARNESS

Description Camera-Rear view

Location RH side of tailgate, behind trim panel

Wire chart

CAV	CSA	COL	CCT	DESTN
1	0.35	BK	(ICRAB/ICRAE)+J3KAB	C49M
2	0.35	BK	(ICRAB/ICRAE)+J3KAB	S4D152B
3	0.35	BK	(ICRAB/ICRAE)+J3KAB	C49M
4	0.35	BK	(ICRAB/ICRAE)+J3KAB	C49M

CAV	CSA	COL	CCT	DESTN
6	0.5	BK	(ICRAB/ICRAE)+J3KAB	C49F
SCR	0.5	SCR	(ICRAB/ICRAE)+J3KAB	C49F