

c2JpbGV0c2t5aTsyMDIxLTA2LTAyVDE1OjQ2OjQ5LjMzMVo7MTg1LjIxMC44NiI4yMjtTQUxDQTJCTjFKSDc1OTUwOA==

G1D130C : Ground

Connector Face





Connector
G1D130C
C1MC19
C1RW01A
C1CA01A
C1CA13B

Housing	**Serviceable Overlay not available**
Engineering Part Number	2S6T-14463-EA
Service Part Number	NA
Colour	TIN PLATED
Cavities	1
Harness	ENGINE COMPARTMENT LH HARNESS
Description	Ground
Location	Rear LH side of engine compartment
Qualifier	LHD condition illustrated

Wire chart and service repair kit information

CAV	CSA	COL	CCT	DESTN	Pre-Terminated Lead	Extract Tool	Crimpers	Wire Stripper	Heat Shrink Sleeve	Ident Sleeve	Splice
1	4.0	BK-YE	ALL	C1CA01A	418-780	-	418-116A	418-672	418-105	418-114	418-109